参考 - 1 項目別·年度別地下水質調査結果

区分	年	概況調査			汚染井	戸周辺地	区調査	定期モニタリング調査			
項目	度	調査井戸 (本)	超過数 (本)	超過率 (%)	調査井戸 (本)	超過数 (本)	超過率	調査井戸 (本)	超過数	超過率	
	元	68	0	0				34	0	0	
	2	86	0	0				37	0	0	
	3	102	0	0				41	0	0	
	4	13	0	0				150	0	0	
	5	9	0	0				156	0	0	
	<u>6</u> 7							159 159	0	0	
	8							159	0	0	
カドミウム	9							161	0	0	
77.32	10	4	0	0	17	0	0	159	0	0	
	11							159	0	0	
	12							87	0	0	
	13							78	0	0	
	14							82	0	0	
	15							101	0	0	
	16							89	0	0	
	17 =	88	0	0			 	76 34	0	0	
	五	100	0	0			1	37	0	0	
	3	111	0	0				41	0	0	
	4	47	0	0		1		150	0	0	
	5	3	0	0				156	0	0	
	6							159	0	0	
	7							159	0	0	
A	8							159	0	0	
全シアン	9		_	_		_		161	0	0	
	10	5	0	0	17	0	0	159	0	0	
	11							159	0	0	
	12							87 78	0	0	
	14							82	0	0	
	15							101	0	0	
	16							89	Ö	0	
	17							76	0	0	
	元	76	0	0				34	0	0	
	2	93	0	0				37	0	0	
	3	118	0	0				41	0	0	
	4	19	0	0				150	0	0	
	5	18	0	0	1	0	0	156	0	0	
	<u>6</u> 7	2	0	0	9	0	0	159 159	1	1.2 0.6	
	8				13	0	0	159	0	0.0	
鉛	9				10	0		161	0	0	
2 H	10	12	0	0	17	0	0	159	0	0	
	11						<u> </u>	159	1	0.6	
	12				9	0	0	87	1	1.1	
	13						ļ	78	0	0	
	14						ļ	82	0	0	
	15				1		 	101	0	0	
	16 17						1	89 76	1	1.3	
	元	66	0	0			1	34	0	0	
	2	111	0	0				37	0	0	
	3	121	0	0			<u> </u>	41	0	0	
			0	0				150	0	0	
	4	8	U		1					0	
	<u>4</u> 5	6	0	0				156	0	U	
	5 6			0				159	0	0	
	5 6 7	6	0					159 159	0	0	
)./#.t= /	5 6 7 8	6	0					159 159 159	0 0	0 0 0	
六価クロム	5 6 7 8 9	6 3	0	0	47			159 159 159 161	0 0 0 0	0 0 0 0	
六価クロム	5 6 7 8 9	6	0		17	0	0	159 159 159 161 159	0 0 0 0	0 0 0 0	
六価クロム	5 6 7 8 9 10	6 3	0	0	17	0	0	159 159 159 161 159 159	0 0 0 0 0	0 0 0 0 0	
六価クロム	5 6 7 8 9 10 11	6 3	0	0	17	0	0	159 159 159 161 159 159 87	0 0 0 0 0 0	0 0 0 0 0 0	
六価クロム	5 6 7 8 9 10 11 12 13	6 3	0	0	17	0	0	159 159 159 161 159 159 159 87 78	0 0 0 0 0 0	0 0 0 0 0 0	
六価クロム	5 6 7 8 9 10 11	6 3	0	0	17	0	0	159 159 159 161 159 159 87	0 0 0 0 0 0	0 0 0 0 0 0	
六価クロム	5 6 7 8 9 10 11 12 13	6 3	0	0	17	0	0	159 159 159 161 159 159 159 87 78 82	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	

参考 - 1 項目別·年度別地下水質調査結果

	区分	年	年 概況調査			汚染井	戸周辺地	区調査	定期モニタリング調査			
項目		度	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数(本)	超過率	
		元	57	0	0	53	3	5.7	34	0	0	
		2	86	0	0	31	1	3.2	37	1	2.7	
		3	89	0	0	16	0	0	41	1	2.4	
		4	13	0	0	24	0	0	186	5	2.7	
		5	6	0	0	8	1	12.5	191	34	17.8	
		6				6	0	0	205	46	22.4	
		<u>7</u> 8				-			206	42 39	20.4 19	
	砒 素	9							205 208	56	26.9	
	ᄣᅓ	10				17	0	0	206	44	21.4	
		11				1			205	29	14.1	
		12				49	11	22.4	131	36	27.5	
		13							124	37	29.8	
		14							126	38	30.2	
		15			L				146	40	27.4	
		16	60	1	1.7	-	_	20.0	133	41	30.8	
		17 =	44	2	4.5	7	2	28.6	215	33	15.3	
		<u>兀</u> 2	65 104	0	0	1		1	34	0	0	
		3	104	0	0	1		 	41	0	0	
		4	8	0	0			1	150	0	0	
		5	6	0	0	1		1	156	0	0	
		6							159	0	0	
		7							159	0	0	
		8							159	0	0	
	総水銀	9							161	0	0	
		10	8	0	0	17	0	0	159	0	0	
	11						1	159	0	0		
		12				-		1	87	0	0	
		13 14							78 82	0	0	
		15							101	0	0	
		16							89	0	0	
		17							73	0	0	
		元	27	0	0				24	0	0	
		2	35	0	0				37	0	0	
		3	69	0	0				41	0	0	
		4	_	_	_				48	0	0	
		5	3	0	0				39	0	0	
		<u>6</u> 7				1		+	56 56	0	0	
		8						 	56 46	0	0	
	РСВ	9				1		 	44	0	0	
		10						1	59	0	0	
		11							58	0	0	
		12							42	0	0	
		13							48	0	0	
		14				1		1	56	0	0	
		15				1		1	46	0	0	
		16				1		1	44	0	0	
		17				<u> </u>		 	11	0	0	
		<u>5</u>	119	0	0	8	0	0	53 62	0	0	
		7	132	0	0	0	U	1 0	63	0	0	
		8	128	0	0	13	0	0	62	0	0	
		9	139	0	0	<u>.</u>	Ť	Ť	50	0	0	
		10	99	0	Ö	27	0	0	59	0	Ö	
3	ブクロロメタン	11							64	0	0	
		12							85	0	0	
		13							96	0	0	
		14				1		1	82	0	0	
				1				. 00		. ^		
		15 16				-		-	86 103	0	0	

参考 - 1 項目別·年度別地下水質調査結果

区分	年	概況調査			汚染井	戸周辺地	区調査	定期モニタリング調査			
項目	度	調査井戸 (本)	超過数	超過率	調査井戸	超過数	超過率	調査井戸 (本)	超過数	超過率	
	4	7	0	0	(-+-)	(-+-)	(70)	150	0	0	
	5	6	0	0				156	0	0	
	6	1	0	0	8	0	0	165	0	0	
	7	132	0	0	17	1	5.9	181	1	0.6	
•	9	128 139	0	0	13	0	0	191 192	0	0	
四塩化炭素	10	133	- 0	U	2	0	0	153	0	0	
110000	11				_			181	Ö	0	
	12							95	0	0	
	13							107	0	0	
	14 15							93 96	0	0	
	16							104	0	0	
	17							84	0	0	
	5							53	0	0	
	6	119	1		8	0	0	62	0	0	
	7	132	0	0		_		79	0	0	
	8	128	0	0	13	0	0	62	0	0	
	9 10	139	0	0	27	0	0	67 48	0	0	
1,2-ジクロロエタン	11					U	"	66	0	0	
1,2) 100 2 / 2	12							85	0	0	
	13						1	96	0	0	
	14							82	0	0	
	15							86	0	0	
	16							103	0	0	
	17							174	0	0	
	5 6	119	0	0	8	0	0	53 174	3	1.7	
	7	132	0	0	- 0	- 0	-	179	4	2.2	
	8	128	0	0	13	0	0	186	2	1	
	9	139	0	0				182	1	0.5	
	10				38	0	0	165	2	1.2	
1,1-ジクロロエチレン	11	14	0	0				171	1	1.7	
	12 13							166 174	2	0.6 1.1	
	14							262	2	0.8	
	15							155	2	1.3	
	16							169	2	1.2	
	17							214	3	1.4	
	5							53	0	0	
	6	119	1	0.8	8	0	0	174	7	4	
•	7 8	132 128	0	0	13	0	0	179 186	9	5 3.2	
	9	139	0	0	13	0	- 0	182	9	4.9	
	10	18	0	0	38	0	0	165	7	4.2	
シス-1,2-ジクロロエチレン	11	14	0	0				171	4	2.3	
	12				-		ļ	194	5	2.5	
	13				-		1	198	5 7	2.5	
	14 15						1	220 185	5	3.2 2.7	
	16							190	3	1.6	
	17							214	4	1.9	
	元	501	0	0	6	0	0	201	0	0	
	2	703	0	0	19	0	0	280	0	0	
	<u>3</u>	1351 540	0	0	52 100	0	0	304 500	0	0	
	5	514	0	0	67	0	0	559	0	0	
	6	176	0	0	47	0	0	577	0	0	
	7	215	0	0	14	0	0	581	0	0	
444 1115 5	8	188	0	0	13	0	0	553	0	0	
1,1,1-トリクロロエタン	9	226	0	0	24	0	0	E40	0		
	10 11	14	0	0	38	0	0	519 476	0	0	
	12	1-7					<u> </u>	185	0	0	
	13							202	1	0.5	
	14							150	0	0	
	15	1	l		1	l	1	180	0	0	
	16							201	0	0	

参考 - 1 項目別·年度別地下水質調査結果

区分	年	概況調査			汚染井	戸周辺地	区調査	定期モニタリング調査			
項目	度	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	
	5	` '				` '		53	0	0	
	6	119	0	0	8	0	0	62	0	0	
	7	132	0	0	40	_		63	0	0	
	8	128 139	0	0	13	0	0	62	0	0	
1.1.2-トリクロロエタン	9 10	139	0	0	2	0	0	67 65	0	0	
1,1,2-19700277	11						-	64	0	0	
	12							85	0	0	
	13							96	0	0	
	14							82	0	0	
	15						1	86	0	0	
	16 17							103 84	0	0	
	- 光	501	0	0	6	0	0	201	24	11.9	
	2	703	0	0	19	0	0	292	23	7.9	
	3	1351	0	Ö	62	Ö	0	316	34	10.8	
	4	540	1	0.2	100	0	0	512	31	6.1	
	5	514	0	0	67	0	0	571	30	5.3	
	6	173	0	0	47	0	0	584	28	4.7	
	7	215	0	0	14	0	0	588	25	4.3	
トリクロロエチレン	9	188 226	0	0	13 24	0	0	560 556	18 16	3.2 2.8	
トリクロロエテレン	10	220	U	U	38	0	0	526	11	2.1	
	11	14	0	0	- 00	-		483	11	2.3	
	12			, i				313	10	3.2	
	13							320	9	2.8	
	14							310	9	2.9	
	15							324	9	2.8	
	16							331	5	1.5	
	17	E01	0	0	6	0	0	283 201	66	1.4	
	<u>兀</u>	501 703	1	0.1	6 19	0	0	292	76	32.8 26	
	3	1351	0	0.1	52	0	0	316	70	22.2	
	4	540	5	0.9	178	5	2.8	510	73	14.3	
	5	514	2	0.4	67	1	1.5	564	68	12.1	
	6	175	0	0	47	1	2.1	577	76	13.1	
	7	215	0	0	14	0	0	581	67	11.5	
,,	8	188	0	0	13	0	0	554	63	11.3	
テトラクロロエチレン	9	226	0	0	24	0	0	554	59	10.6	
	10	14	0	0	1		1	524 481	52 48	9.9	
	12	14	U	U				346	40	121	
	13						1	350	39	11.1	
	14				1		1	436	37	8.5	
	15							351	34	9.7	
	16							356	35	9.8	
	17							274	34	12.4	
	5	440		_	L .		<u> </u>	53	0	0	
	7	119 132	0	0	8	0	0	58 59	0	0	
	8	128	0	0	1	0	0	58	0	0	
	9	139	0	0		0		63	0	0	
	10	14	0	0	1		1	61	0	0	
1,3-ジクロロプロペン	11							58	0	0	
	12							81	0	0	
	13							91	0	0	
	14				1		1	82	0	0	
	15				1		1	82	0	0	
	16				 	-	1	99	0	0	
	17	l	l	1	1	1	1	80	0	0	

参考 - 1 項目別·年度別地下水質調査結果

区分	年	10000000000000000000000000000000000000				戸周辺地	区調査	定期モニタリング調査			
項目	度	調査井戸 (本)	超過数 (本)	超過率	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	
	5							53	0	0	
	6	119	0	0				58	0	0	
	7	132	0	0				58	0	0	
	8	128	0	0			1	58	0	0	
	9 10	139	0	0			1	63 61	0	0	
チウラム	11						1	58	0	0	
7 3 7 1	12							77	0	0	
	13							83	0	0	
	14							91	0	0	
	15							80	0	0	
	16 17						1	79 115	0	0	
	5							53	0	0	
	6	119	0	0				58	0	0	
	7	132	0	0				58	0	0	
	8	128	0	0				58	0	0	
	9	139	0	0			1	63	0	0	
2,7275	10			-	1	-	1	61	0	0	
シマジン	11			1	1	1	1	58 77	0	0	
	13					<u> </u>	†	83	0	0	
	14							91	0	0	
	15							80	0	0	
	16							79	0	0	
	17							115	0	0	
	5 6	119	0	0				83 58	0	0	
	7	132	0	0				58	0	0	
	8	128	0	0				58	0	0	
	9	139	0	0				63	0	0	
~\	10							61	0	0	
チオベンカルブ	11						1	58 77	0	0	
	13							83	0	0	
	14							91	0	0	
	15							80	0	0	
	16							79	0	0	
	17							115	0	0	
	<u>5</u>	119	0	0	8	0	0	53 62	0	0	
	7	132	0	0	0	- 0	- 0	63	0	0	
	8	128	0	0	13	0	0	61	0	0	
	9	139	0	0				66	0	0	
** \ . L* \ .	10				2	0	0	65	0	0	
ベンゼン	11				13	3	23.1	58 83	0	0	
	13							108	3	2.8	
	14				1		†	93	3	3.2	
	15							97	2	2.1	
	16			1			1	114	1	0.9	
	17				<u> </u>	 	 	95	1	1.1	
	<u>5</u>	119	0	0	-	 	1	53 62	0	0	
	7	132	0	0	1		1	62	0	0	
	8	128	0	0				61	0	0	
	9	139	0	0	6	1	16.7	72	2	2.8	
4 1 3:	10	10	0	0	17	0	0	66	0	0	
セレン	11			1	1	1	1	65 92	0	0	
	13			t		t	1	84	0	0	
	14							87	0	0	
	15							95	0	0	
	16				ļ			83	0	0	
	17							82	0	0	

参考 - 1 項目別·年度別地下水質調査結果

区分	年	概況調査			汚染井	戸周辺地	!区調査	定期モニタリング調査			
項目	度	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	調査井戸 (本)	超過数	超過率	
	6	129	7	5.4				159	4	2.5	
	7	132	5	3.8				159	7	4.4	
	8	128	5	3.9				160	6	3.8	
	9	139	6	4.3				161	3	1.9	
硝酸性窒素·亜硝酸性窒	10	412	6	1.5	195	26	13.3	159	6	3.8	
	11	463	28	6				241	31	12.9	
	12	330	5	2	433	16	3.7	273	41	15.0	
	13							293	44	15.0	
	14							289	38	13.2	
	15							343	43	12.5	
	16	250	2	0.8				330	41	12.4	
	17	291	6	2.1	67	17	25.4	347	45	13.0	
	10	51	1	2	10	3	30				
	11							162	8	4.9	
ふっ素	12				317	78	24.6	160	5	3.1	
	13	472	17	3.6	108	17	15.7	110	27	24.5	
	14	433	3	1.0	25	0	0	123	38	30.9	
	15	216	7	3.2	60	8	13	142	37	26.1	
	16							136	34	25.0	
	17	291	3	1.0	24	8	33.3	287	47	16.4	
	10	41	0	0				450		1.0	
	11				100			159	2	1.3	
はこま	12	470		0.0	120	1 7	0.8	157	2	1.3	
ほう素	13	472	1	0.2	22	7	63.6	103	2	1.9	
	14	433	0	0	25	0	0	109	3	2.8	
	15	216	1	0.5	60	2	3.3	116	5	4.3	
	16							105	3	2.9	
	17							221	3	1.4	

参考-2 地下水の水質に係る環境基準

項目	N貝に添る環境基準 環境基準 [mg/L]	報告下限値 [mg/L]
カドミウム	0.01以下	0.001
全シアン	検出されないこと	0.1
鉛	0.01以下	0.005
六価クロム	0.05以下	0.04
砒素	0.01以下	0.005
総水銀	0.0005以下	0.0005
アルキル水銀	検出されないこと	0.0005
P C B	検出されないこと	0.0005
ジクロロメタン	0.02以下	0.002
四塩化炭素	0.002以下	0.0002
1,2-ジクロロエタン	0.004以下	0.0004
1 , 1 - ジクロロエチレン	0.02以下	0.002
シス - 1 , 2 - ジクロロエチレン	0.04以下	0.004
1,1,1-トリクロロエタン	1以下	0.0005
1,1,2-トリクロロエタン	0.006以下	0.0006
トリクロロエチレン	0.03以下	0.002
テトラクロロエチレン	0.01以下	0.0005
1,3-ジクロロプロペン	0.002以下	0.0002
チウラム	0.006以下	0.0006
シマジン	0.003以下	0.0003
チオベンカルブ	0.02以下	0.002
ベンゼン	0.01以下	0.001
セレン	0.01以下	0.001
硝酸性窒素及び亜硝酸性窒素	10以下	0.01
ふっ素	0.8以下	0.08
ほう素	1以下	0.01